


- Button function:
 - in/mm: short press for inch/metric conversion
long press to change measuring direction
 - ABS: short press for absolute/incremental measurement
long press to preset data
 - 0/ON: short press to turn on when power is off
short press to set zero when power is on
long press to turn off
- Keep preset data in memory after restart
- CR1632 battery, automatic power off
- Data output
- Optional accessory: data output cable (code **7315-50M**, **7302-40M**, **7305-40M**), contact points



2114-51F



| Code | Range | Resolution | Accuracy | Hysteresis | Remark |
|-------------------|----------|------------------|----------|------------|-----------|
| 2114-5F * | 5mm/0.2" | 0.01mm/0.0005" | 20µm | 10µm | flat back |
| 2114-51F * | 5mm/0.2" | 0.001mm/0.00005" | 5µm | 2µm | flat back |

* Supplied with manufacturer inspection certificate